

SAFE Notice 2025

112

MORISSET - WYONG

On Thursday night/Friday morning, 6 – 7 February 2025

In conjunction with Special Train Notice No. 0201 - 2025 the following Safeworking arrangements will apply:

PILOT STAFF WORKING (UP MAIN NORTH LINE) MORISSET – WYONG

If rail traffic is required to travel in both directions on the Up Main North line, pilot staff working in accordance with NSY 516 must be introduced between Signal No.76.6 at Morisset and Signal No. WG.30 at Wyong.

MORISSET SIGNAL BOX

Morisset Signal box must be attended and switched into local control for the duration of pilot staff working.

A Qualified Worker must be provided to act as Signaller and take control of the Signal box at Morisset.

WYONG (108 CROSSOVER)

A Qualified Worker must be provided to take control of 108 crossover at Wyong, act as Signaller at that location and operate the crossover in accordance with NSY 516.

SYDNEY, 23 JANUARY 2025 **DIRECTOR NETWORK STANDARDS, SYSTEMS & QUALITY SYDNEY TRAINS**

Returned to Controlling Manager: Date: Signed:



(Cut along this line and forward the detached receipt to your Controlling Manager)

To Controlling Manager: Date: Signed:

Received SAFE Notice No. 112 – 2025 Date: Signed:

Name (print): Location:

(Controlling Manager to retain this Acknowledgement of Receipt of the SAFE Notice for record purposes for 90 days)