

# weekly notice

Monday, 12 September 2022 Sunday, 18 September 2022





# See online for all Safeworking Information

www.railsafe.org.au

Safeworking information, including Weekly Notices and SAFE Notices, is available on the RailSafe website.

By accessing Weekly Notices and SAFE Notices online, you will receive safety information more quickly. Weekly Notices remain on the RailSafe website for two years; Permanent and Temporary SAFE Notices remain online as long as they are current.

Anyone needing back issues of Weekly Notices and SAFE Notices should contact the Network Rules unit.

If you are outside Sydney Trains, you can reach the RailSafe website via the following address:

www.railsafe.org.au

Other Safeworking documents, such as Network Rules, Network Procedures, Network Local Appendices, Safeworking Policies, SafeTracks flyers, and contractor information are also available online.

# Director Network Standards, Systems & Quality Sydney Trains

Continued on next page



PUBLICATION DEADLINES AND SUBMISSION OF ARTICLES	4
DUNMORE (ILLAWARRA) - WESTRACE MK2 INTERLOCKING UPGRAD <b>(DIAGRAM)</b>	Е 5
MTMS STAGE 2 - SOUTH COAST WORKS LNIF SOUTH OF WOLLONGONG – KIAMA DOWN SIDING <b>(DIAGRAM)</b>	6
MTMS2 SYDNEY AREA (ERSKINEVILLE) –STAGE 4 [REMOVAL OF 676 CROSSOVER] <b>(DIAGRAM)</b>	8
EDGECLIFF (EASTERN SUBURBS RAILWAY (ESR)) – REMOVAL OF 905 906 POINTS, SY752 SIGNAL AND CONVERSION OF CONTROLLED SIGNALS TO AUTOMATIC <b>(DIAGRAM)</b>	& 9
MTMS2 – ERSKINEVILLE JUNCTION – SPEED SIGN CHANGES	11
STATUS OF TOM NOTICES	13
STATUS OF PERMANENT SAFE NOTICES	15
STATUS OF NETWORK MANUALS AND FORMS	16
DISTRIBUTION OFFICERS	18

CONTENTS



# **PUBLICATION DEADLINES AND SUBMISSION OF ARTICLES**

Dates of the next three Weekly Notices and deadlines for articles are:

Weekly Notice	For Week	Deadline
39	19/09/2022 – 25/09/2022	23/08/2022
40	26/09/2022 – 02/10/2022	30/08/2022
41	03/10/2022 – 09/10/2022	06/09/2022

To meet printing and distributing schedules, articles for a Weekly Notice must be received by its deadline.

Articles submitted after a deadline will be published in the next issue of the Weekly Notice. This may result in information not being distributed in time for it to be acted upon.

When submitting articles, please include your name, position title, telephone numbers and email address at the end of the articles as shown below:

# Steve Swanson

Network Rules Specialist Tel: 02 8922 4183 (external) 2 4183 (internal) Email: stephen.swanson@transport.nsw.gov.au



# DUNMORE (ILLAWARRA) - WESTRACE MK2 INTERLOCKING UPGRADE

Commencing at 15:31 hours on **Friday, 30 September 2022** and continuing until 00:29 hours on Monday, 3 October 2022, the following works will be carried out:

- Removal of Drivers Pushbuttons at Dunmore on 43.3, 43.4, 43.5, 43.6, 43.21, 43.23, 43.25, 43.26, 43.27, 43.28, 43.30 & 43.32
   Signals.
- The existing WESTRACE MK1 interlocking in the Dunmore area will be replaced with a signalling equipment. WESTRACE MK2 to control existing
- The Wollongong Control Panel will have some minor changes:
  - Track 29CT at Oak Flats will be renamed to 29CT-DT
  - The alarms for the Dunmore and Minnamurra Fire System and Intruder will be removed

The new arrangement are shown in the attached Drivers Diagrams.

VER 110722


# Drivers Diagram VER 220621


## Patricia Roser

Commissioning Manager Signalling, Sydney Trains Mobile: 0438461351 Email: PATRICIA.ROSER@transport.nsw.gov.au

## **Richard Fang**

Signalling Design Engineer Siemens Mobility Mobile: 0412141804 Email: Richard.Fang@siemens.com







# MTMS STAGE 2 - SOUTH COAST WORKS LNIF SOUTH OF WOLLONGONG – KIAMA DOWN SIDING

Commencing at 02:00 hours on **Saturday, 1 October 2022,** and continuing until 24:00 hours on Sunday, 5 March 2023, the following works will be carried out:

- The Kiama Down Siding will be booked out of use between the abovementioned dates. Final possession handback will be 24:00 hours on Sunday, 4 March 2023.
- During this period,
  - 54A Point End will be clipped, spiked, XL locked and detected in the normal position.
  - A temporary stop block will be installed countryside of 54B points and removed later as part of final handback
- 54B catchpoints and Points motor will be renewed.
- The Down Siding will be extended with
  - The existing timber buffer stop and light removed.
  - Approx. 216m of total standing room
  - New 54B Catchpoints and 54B points motor
  - New Friction Buffer Stop installed at 119.675km
  - New post mounted LED buffer stop White over Red light, adjacent to new fixed train stop at 119.672km
  - New Drivers Walkway and Lighting
  - New post mounted 10 car marker sign at 119.667km

A Drivers Diagram showing the new arrangement appears in this Weekly Notice.

# VER 24052022 DIAGRAM VER 24052022

## **Matthew Ward**

Commissioning Engineer, JMDR Mob: 0403 689 614 Email: matthew.ward@jmdr.com .com


WN 38 — 12 September 2022



# Vinish Mariappan

Design Delivery Manager Mob: 0470 655 177 Email: vinish.mariappan@jmdr.com

#### Document No. MTMS2S-JMDR-KMY-SE-DRG-300003 **Revision: 00**



**OFFICIAL** 

VER. 240522



# MTMS2 SYDNEY AREA (ERSKINEVILLE) – STAGE 4 [REMOVAL OF 676 CROSSOVER]

#### \*\*THE FOLLOWING WORK DID NOT TAKE PLACE AS ADVERTISED IN WN 11-2022 AND WN12-2022. IT WILL BE PERFORMED ON THE DATE BELOW\*\*

Commencing at 02:00 hours on Saturday, **17 September 2022,** and continuing until 02:00 hours on Monday, 19 September 2022, the following works will be carried out:

- 676 crossover which is currently booked out of use will be physically removed.
- ATRICS changes to remove 676 crossover from the ESR panel will be made 24 September 2022.
- ATRICS changes to remove 676 crossover from the Illawarra panel will be made 27 December 2022.

The following infrastructure will be booked back into use:

- Points 681A/B, 682A/B, 683A/B and 684A/B.
- Signal Routes 537(M)B, 537(S)B, 546(M)B and 546(S)B.

A Drivers Diagram showing the altered arrangement is provided with this Weekly Notice.


## **DRIVERS DIAGRAM VER 31012022**


## **Mark Skribins**

Signalling Commissioning Engineer Mobile: 0412 520 806 Email: mark.skribins@jhg.com.au

# **Steve Cotton**

Engineering Manager, JMDR Mobile: 0412 644 832 Email: steve.cotton@jmdr.com





			_
SIGNAL	ROUTE	DESTINATION	IND.
539	(M)	DOWN ILLAWARRA	-
55,	(S)	DOWN ILLAWARRA	-
		-	
SIGNAL	ROUTE	DESTINATION	IND.
540	(M)	UP ILLAWARRA	-
0.10	(S)	UP ILLAWARRA	-
			-
SIGNAL	ROUTE	DESTINATION	IND.
541	(M)	DOWN ILLAWARRA	-
011	(S)	DOWN ILLAWARRA	-
SIGNAL	ROUTE	DESTINATION	IND.
= + 0	-	-	-
542	В	EVELEIGH YARD	Y



# EDGECLIFF (EASTERN SUBURBS RAILWAY (ESR)) – REMOVAL OF 905 & 906 POINTS, SY752 SIGNAL AND CONVERSION OF CONTROLLED SIGNALS TO AUTOMATIC

Commencing at 0200 hours on **Saturday, 24 September 2022** and continuing until 0200 hours on Monday 26 September 2022, the following work shall be carried out:

- SY752 Signal located on the Down ESR will be removed.
- The Signals mentioned in the table below will be converted from controlled to automatic, renamed and an 'A' plate sign or 'A' light added to each signal, with remaining form of each signal unaltered.

Existing Signal Name	New Name	Signal	SHUNT REMOVED	'A' LIGHT	'A' PLATE
SY 743	ES4.51		N/A		YES
SY 745	ES4.59		N/A		YES
SY 749	ES4.65		YES		YES
SY 751	ES4.71		N/A		YES
SY 754	ES4.72		YES	YES	
SY 755	ES4.91		N/A	YES	

• Signals ES4.72 on the Up ESR and ES4.91 on the Down ESR will each have a sign fitted that is as shown below.

"WHEN 'A' I	_IGHT I	S OUT TH	HIS S	IGNAL
MUST NO	Г ВЕ	PASSED	AT	STOP
WITHOUT	AUTHO	DRITY F	ROM	THE
SIGNALLEF	2"			



- The ATRICS panel will be updated to reflect the alterations mentioned above.
- Signals ES4.72 and ES4.91 will also be provided with an emergency replacement function on ATRICS.

Refer to the attached Drivers Diagram for the new layout at Edgecliff.


# VER24062022

## **Rhoel Del Rosario**

Commissioning Engineer Signalling, Project Engineering & Support, Major Works Sydney Trains Mob: 0413450361 Email: rhoel.delrosario@transport.nsw.gov.au

# Barry O'Donnell

Senior Signal Design Engineer
Mob: 0406769650
Signalling & Control Systems, Engineering & System Integrity, Maintenance
Email: barry.o'donnell@transport.nsw.gov.au





# **MTMS2 – ERSKINEVILLE JUNCTION – SPEED SIGN CHANGES**

On **Sunday 18 September 2022 (WE12),** the following speed signs will be commissioned:

# Section 8a Central - Hurstville Illawarra Line

	KILO-	DO	WN	U	Р
	MET-	Nor-		Nor-	
	RAGE	mal	XPT	mal	XPT
Existing	2.213	Illawa	irra Ju	nction	
Existing	2.300			50	
Amend	2.360			X25	
To Read	2.390			X25	
Amend	2.390	50			
To Read	2.423	50			
Insert	2.410	X40		681/	A Pts
	2.538			68	3A
Insert	2.550	X40		Pts	<b>O</b>
Existing	2.808	Erski	neville	Junct	ion
Existing	2.820			X25	
Existing	2.881	Erski	neville		
Existing	2.970	65			
Existing	3.265			65	
Existing	3.809	St Pe	ters		
Oown sign on Up Main					



## Section 8b **Central - Hurstville** Illawarra Local Line

	KILO-	DOWN	U	Ρ
	MET-	Nor-	Nor-	
	RAGE	mal XPT	mal	XPT
Existing	0.000	Central		
Remove	0.814	60		
Existing	0.885		50	
Insert	0.891	60		
Existing	1.299	Redfern		
Existing	1.610		60	
Existing	2.213	Illawarra Ju	Inction	l
	2.520	682B Pts		
Insert	2.520	0	X40	
Insert	2.632	684B Pts	X40	
Existing	2.808	Erskineville	e Junct	ion
Existing	2.881	Erskineville	<b>;</b>	
Existing	3.240	70		
Existing	3.809	St Peters		
Existing	4.700		65	
Existing	5.050	734 Pts	X25	
Existing	5.100	55		
Existing	5.113	0	X40	
Existing	Existing 5.308 Sydenham			
	U Dow	n sign on Up	Local	
	0 001			

• Up sign on Down Local

# **Cameron Ly**

Principal Track Design Engineer, Engineering System Integrity Phone: 9536 3454

# Email: Cameron.Ly@transport.nsw.gov.au

# Jamie Ha

Designer, Track Design, Engineering System Integrity Mobile: 0448 701 734 Email: Jamie.ha@transport.nsw.gov.au



# STATUS OF TOM NOTICES

001 - 2007         Introduction of TOM Notices         13/09/07         13/09/07           018 - 2007         Emergency equipment boxes Rail         01/11/07         19/11/07           010 - 2012         48 Class: Train Operations Manual (TOM)         25/10/12         04/11/12           003 - 2013         AG Class: Wheels         07/02/13         10/02/13         09/06/13           004 - 2016         OMET 200: Minimum Standards for Electric Trains         30/05/13         09/06/13           004 - 2016         OMET 220: Wheelslip light indications         20/02/14         02/03/14           004 - 2016         OMET 220: Wheels Distign Mindow Glass         06/04/17         16/04/17           005 - 2017         TWP 150: Damaged or Missing Window Glass         06/07/17         16/07/17           008 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           005 - 2018         TW	Number	Title	Issued	Effective
010 - 2012         48 Class: Train Operations Manual (TOM)         25/10/12         04/11/12           003 - 2013         48 Class: Wheels         07/02/13         10/02/13           015 - 2013         OMET 200: Minimum Standards for Electric Trains         30/05/13         09/06/13           002 - 2014         OMET 200: Wheelslip light indications         20/02/14         02/03/14           004 - 2016         OMET 262: Failure of Train Management System         14/07/16         24/07/16           001 - 2017         Incorporation of Waratah, Oscar and Millennium TOM         19/01/17         29/01/17           Notices and SAFE Notices into the TOM         06/07/17         16/07/17         16/07/17           004 - 2017         TWP 150: Damaged or Missing Window Glass         06/04/17         16/07/17           005 - 2017         TWP 174 lce Radio         20/07/17         31/07/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           005 - 2019         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           005 - 2019	001 – 2007	Introduction of TOM Notices	13/09/07	13/09/07
003 - 2013         48 Class: Wheels         07/02/13         10/02/13           015 - 2013         OMET 200: Minimum Standards for Electric Trains         30/05/13         09/06/13           004 - 2016         OMET 220: Wheelslip light indications         20/02/14         02/03/14           004 - 2016         OMET 220: Failure of Train Management System         14/07/16         24/07/16           001 - 2017         Incorporation of Waratah, Oscar and Millennium TOM         19/01/17         29/01/17           005 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/04/17           004 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/07/17           004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           005 - 2019         TWP 196: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         TWP 190: Automatic Train Protection         06/03/19         24/03/19           007 - 2019	018 – 2007	Emergency equipment boxes Rail	01/11/07	19/11/07
015 - 2013         OMET 200: Minimum Standards for Electric Trains         30/05/13         09/06/13           002 - 2014         OMET 220: Wheelslip light indications         20/02/14         02/03/14           004 - 2016         OMET 262: Failure of Train Management System         14/07/16         24/07/16           001 - 2017         Incorporation of Waratah, Oscar and Millennium TOM         19/01/17         29/01/17           Notices and SAFE Notices into the TOM         19/01/17         16/04/17         16/04/17           005 - 2017         TWP 175: Wayside Train Condition Monitoring         06/04/17         16/07/17           004 - 2017         TWP 174 Lee Radio         20/07/17         31/07/17           018 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           008 - 2018         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           0	010 – 2012	48 Class: Train Operations Manual (TOM)	25/10/12	04/11/12
002 - 2014         OMET 220: Wheelslip light indications         20/02/14         02/03/14           004 - 2016         OMET 262: Failure of Train Management System         14/07/16         24/07/16           001 - 2017         Incorporation of Waratah, Oscar and Millennium TOM Notices and SAFE Notices into the TOM         19/01/17         29/01/17           005 - 2017         TWP 150: Damaged or Missing Window Glass         06/04/17         16/04/17           008 - 2017         TWP 174: Ice Radio         20/07/17         31/07/17           004 - 2017         TWP 174: Ice Radio         20/07/17         31/07/17           014 - 2017         Amendment to OMET 200         14/12/17         24/12/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           006 - 2018         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 190. Automatic Train Protection         06/03/19         24/03/19           007 - 2019	003 – 2013	48 Class: Wheels	07/02/13	10/02/13
004 - 2016         OMET 262: Failure of Train Management System         14/07/16         24/07/16           001 - 2017         Incorporation of Waratah, Oscar and Millennium TOM Notices and SAFE Notices into the TOM         19/01/17         29/01/17           005 - 2017         TWP 150: Damaged or Missing Window Glass         06/04/17         16/04/17           008 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/07/17           004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           012 - 2018         Control Circuit Failure         23/08/18         20/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           006 - 2018         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         TWP 130 Epfective wheels         06/03/19         24/03/19           007 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           010 - 2019         TWP 190 Automatic Train Sout of service         06/03/19         24/03/19 <td>015 – 2013</td> <td>OMET 200: Minimum Standards for Electric Trains</td> <td>30/05/13</td> <td>09/06/13</td>	015 – 2013	OMET 200: Minimum Standards for Electric Trains	30/05/13	09/06/13
001 - 2017         Incorporation of Waratah, Oscar and Millennium TOM         19/01/17         29/01/17           005 - 2017         TWP 150: Damaged or Missing Window Glass         06/04/17         16/04/17           008 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/07/17           008 - 2017         TWP 174 Lee Radio         20/07/17         31/07/17           018 - 2017         Amendment to OMET 200         14/12/17         24/12/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           03/3/19         OT - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 192 Automatic Train Protection         06/03/19         24/03/19	002 – 2014	OMET 220: Wheelslip light indications	20/02/14	02/03/14
Notices and SAFE Notices into the TOM           005 - 2017         TWP 150: Damaged or Missing Window Glass         06/04/17         16/04/17           008 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/07/17           004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           018 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           005 - 2019         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           007 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 192 Automatic Train Protection         06/03/19         24/03/19           008 - 2019         TWP 192 Disabled trains         06/03/19         <	004 – 2016	OMET 262: Failure of Train Management System	14/07/16	24/07/16
008 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/07/17           004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           018 - 2017         Amendment to OMET 200         14/12/17         24/12/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           006 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           007 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors </td <td>001 – 2017</td> <td></td> <td>19/01/17</td> <td>29/01/17</td>	001 – 2017		19/01/17	29/01/17
008 - 2017         TWP 176: Wayside Train Condition Monitoring         06/07/17         16/07/17           004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           018 - 2017         Amendment to OMET 200         14/12/17         24/12/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           006 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           007 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors </td <td>005 – 2017</td> <td>TWP 150: Damaged or Missing Window Glass</td> <td>06/04/17</td> <td>16/04/17</td>	005 – 2017	TWP 150: Damaged or Missing Window Glass	06/04/17	16/04/17
004 - 2017         TWP 174 Ice Radio         20/07/17         31/07/17           018 - 2017         Amendment to OMET 200         14/12/17         24/12/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           012 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 130 Automatic Train Protection         06/03/19         24/03/19           008 - 2019         TwP 190 Automatic Train Protection         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 152: Operating doors				
018 - 2017         Amendment to OMET 200         14/12/17         24/12/17           012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           017 - 2019         TWP 196: Defective wheels         06/03/19         24/03/19           007 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           008 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 152 Operating doors         14/03/19         24/03/19           014 - 2019         TWP 118 Reporting	004 – 2017			
012 - 2018         Control Circuit Failure         23/08/18         02/09/18           005 - 2018         OMET 242 Reverser handle jams in forward or reverse         18/08/18         28/08/18           006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           007 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           011 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           024 - 2019         TWP 118 Reporting Faults         03/10/19         13/10/19           024 - 20	018 - 2017	Amendment to OMET 200		
006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           007 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           008 - 2019         TWP 194 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           022 - 2019         Exception to WAR 030 – Minimum Standards         03/10/19         13/10/19           024 - 2019         TWP 118 Reporting Faults         01/05/20         08/06/20           004 - 2020         TWP 124 Defective	012 – 2018	Control Circuit Failure		
006 - 2018         OMET 250 Applying power from the rear         18/08/18         28/08/18           008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           007 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           008 - 2019         TWP 194 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           022 - 2019         Exception to WAR 030 – Minimum Standards         03/10/19         13/10/19           024 - 2019         TWP 118 Reporting Faults         01/05/20         08/06/20           004 - 2020         TWP 124 Defective	005 – 2018	OMET 242 Reverser handle jams in forward or reverse		28/08/18
008 - 2018         TWP 154 Responding to incapacitated Driver/Guard         18/08/18         28/08/18           016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           012 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 136 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           011 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           024 - 2020         TWP 124 Defective Rakes         20/05/20         08/06/20           005 - 2020         TWP 126 De	006 – 2018			28/08/18
016 - 2018         Network Rules Operational standards update         17/08/18         27/08/18           005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           012 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 136 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           011 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           014 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 – Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults <td< td=""><td>008 – 2018</td><td></td><td>18/08/18</td><td>28/08/18</td></td<>	008 – 2018		18/08/18	28/08/18
005 - 2019         TWP 106: On Road Performance Assessment         31/01/19         10/02/19           003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           012 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 136 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           022 - 2019         Exception to WAR 030 – Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/07/20	016 - 2018			
003 - 2019         OMET 264: Minimum Tractive Effort Requirements         21/02/19         03/03/19           012 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 136 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           024 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           011 - 2020         TWP 112 Changing ends         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         03/08/20           011 - 2020         TWP 112 Changing ends         20/07/20 <t< td=""><td>005 – 2019</td><td></td><td></td><td></td></t<>	005 – 2019			
012 - 2019         TWP 192: Working Trains Out of service         21/02/19         03/03/19           007 - 2019         TWP 136 Defective wheels         06/03/19         24/03/19           008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           011 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           011 - 2020         TWP 112 Changing ends         20/07/20         03/08/20<	003 - 2019	OMET 264: Minimum Tractive Effort Requirements	1	
008 - 2019         TWP 190 Automatic Train Protection         06/03/19         24/03/19           009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 2	012 – 2019		1	03/03/19
009 - 2019         Train crew relieved in service & relay driver         06/03/19         24/03/19           010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           011 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with dof/12/20         14/12/20           066 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         OMET 254 Topside preparation locations         05/03/21	007 – 2019	TWP 136 Defective wheels	06/03/19	24/03/19
010 - 2019         TWP 152 Disabled trains         06/03/19         24/03/19           011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets f	008 – 2019	TWP 190 Automatic Train Protection	06/03/19	24/03/19
011 - 2019         TWP 156: Operating doors         14/03/19         24/03/19           014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 – Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transitio	009 – 2019	Train crew relieved in service & relay driver	06/03/19	24/03/19
014 - 2019         OSCAR Internal Emergency Door Releases         14/03/19         24/03/19           004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with dof/12/20         14/12/20           061 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	010 – 2019		1	24/03/19
004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	011 – 2019	TWP 156: Operating doors	14/03/19	24/03/19
004 - 2019         TWP 118 Reporting Faults         11/04/19         28/04/19           022 - 2019         Exception to WAR 030 - Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	014 – 2019	OSCAR Internal Emergency Door Releases	14/03/19	24/03/19
022 - 2019         Exception to WAR 030 – Minimum Standards         03/10/19         13/10/19           004 - 2020         TWP 124 Defective Brakes         20/05/20         08/06/20           005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	004 – 2019		11/04/19	28/04/19
005 - 2020         TWP 126 Defective Automatic Brakes         20/05/20         08/06/20           012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	022 - 2019		03/10/19	13/10/19
012 - 2020         WAR 202 Bogie Faults         20/05/20         08/06/20           011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	004 - 2020	TWP 124 Defective Brakes	20/05/20	08/06/20
011 - 2020         TWP 162 Train Crew Bell Signals         02/06/20         15/06/20           014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	005 - 2020	TWP 126 Defective Automatic Brakes	20/05/20	08/06/20
014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	012 - 2020	WAR 202 Bogie Faults	20/05/20	08/06/20
014 - 2020         TWP 112 Changing ends         20/07/20         03/08/20           017 - 2020         Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground         07/12/20         14/12/20           005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	011 - 2020	TWP 162 Train Crew Bell Signals	02/06/20	15/06/20
017 - 2020Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground07/12/2014/12/20005 - 2021OMET 254 Topside preparation locations05/03/2115/03/21006 - 2021TWP 100 Responsibilities of Train Crews23/03/2105/04/21007 - 2021Operation of H sets fitted with ATP10/05/2124/05/21008 - 2021Transition (Emergency couplers on OSCAR trains)14/07/2126/07/21	014 - 2020		20/07/20	
005 - 2021         OMET 254 Topside preparation locations         05/03/21         15/03/21           006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	017 - 2020		07/12/20	
006 - 2021         TWP 100 Responsibilities of Train Crews         23/03/21         05/04/21           007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	005 - 2021		05/03/21	15/03/21
007 - 2021         Operation of H sets fitted with ATP         10/05/21         24/05/21           008 - 2021         Transition (Emergency couplers on OSCAR trains)         14/07/21         26/07/21	006 - 2021			
008 - 2021Transition (Emergency couplers on OSCAR trains)14/07/2126/07/21		· · · · · · · · · · · · · · · · · · ·		
			1	
	011 - 2021	Exception to OMET 200 & 350	17/11/21	29/11/21

WN 38 — 12 September 2022



Number	Title	Issued	Effective
001 - 2022	Use of Automatic train Protection in Millennium trains	23/03/22	03/04/22
002 - 2022	Waratah A & B sets fitted with ATP	23/03/22	03/04/22
005 - 2022	TWP 160 Driver procedure at stations	21/04/22	08/05/22
006 – 2022	Testing of Tangaras fitted with Automatic Train Protection (ATP)	06/07/22	06/07/22
022 – 2022	Withdrawal of redundant TOM notices	22/07/22	08/08/22
023 - 2022	Exception to OMET 252 Topside Preparation Locations	16/08/22	22/08/22



# STATUS OF PERMANENT SAFE NOTICES

Number	Title	Issued	Effective
001 - 2022	Introduction of the NIMP	06/04/22	23/04/22
003 - 2022	Control of the Country Rail Network (CRN) by UGL Regional Linx (UGLRL)	18/07/22	28/07/22
004 - 2022	Use of Signal Key Switches	19/07/22	25/07/22

# Steve Swanson

Network Rules Specialist

Tel: 0428416505

Email: stephen.swanson@transport.nsw.gov.au



# STATUS OF NETWORK MANUALS AND FORMS

Network Manuals

Network Local Appendices	RailSafe Website	Online documents
<b>Operator Specific Procedures</b>	RailSafe Website	Online documents
Network Rules	RailSafe Website	Online documents
Network Procedures	RailSafe Website	Online documents
Forms	RailSafe Website	Online documents (or order as applicable)



#### weekly notice

#### Title

Status Sheet

Date issued

# Train Working Procedures

TWP 100	TN 006 - 2021	April 2021
TWP 102	3	May 2012
TWP 108	4	May 2012
TWP 110	TN 009 - 2019	March 2019
TWP 112	TN 014 - 2020	August 2020
TWP 114	4	November 2015
TWP 116	3	May 2012
TWP 118	TN 004 - 2019	April 2019
TWP 120	3	May 2012
TWP 122	3	May 2012
TWP 124	TN 004 - 2020	May 2019
TWP 126	TN 005 - 2020	May 2019
TWP 128	3	May 2012
TWP 130	3	May 2012
TWP 132	3	May 2012
TWP 134	3	May 2012
TWP 136	TN 007 - 2019	March 2019
TWP 138	4	November 2015
TWP 142	3	May 2012
TWP 144	5	May 2012
TWP 146	3	May 2012
TWP 148	3	May 2012
TWP 150	TN 005 - 2017	April 2017
TWP 152	TN 010 - 2019	March 2019
TWP 154	TN 008 - 2018	July 2018
TWP 156	TN 011 - 2019	March 2019
TWP 158	3	May 2012
TWP 160	TN 005 - 2022	May 2022
TWP 162	TN 011- 2020	May 2019
TWP 164	4	May 2012
TWP 166	3	May 2012
TWP 168	3	May 2012
TWP 170	3	May 2012
TWP 172	4	May 2012
TWP 174	TN 004 - 2017	July 2017
TWP 176	TN 008 - 2017	July 2017
TWP 182	1	November 2015
TWP 184	1	November 2015
TWP 188	1	November 2015
TWP 190	TN 008 - 2019	March 2019
TWP 192	TN 012 - 2019	March 2019



# **DISTRIBUTION OFFICERS**

Sydney Trains

#### Safety and Environment

#### **Train Crew Operations**

#### Manager Day of Operations

S8577 7029

 TCOManagerDayofOperations@transport. nsw.gov.au

**Train Crewing Tim Kelly** Operating Standards Officer

Dimothy.kelly@transport.nsw.gov.au

Amba Francisco Crew Manager – Blacktown/Richmond 42828 amba.francisco@transport.nsw.gov.au

Anthony Robb Crew Area Manager - Flemington 9536 8844 Anthony.robb@transport.nsw.gov.au

**Craig Jackson** Crew Area Manager - Mortdale 42624 Craig.jackson@transport.nsw.gov.au

gov.au

WN 38 — 12 September 2022

#### **Patrick Rhymer**

Acting Crew Area Manager - Campbelltown 91755 patrick.rhymer@transport.nsw. gov.au

#### Rita Kazzi

Acting Crew Area Manager Leppington

63549 rita.kazzi@transport.nsw.gov.au

Rhys Blakey Senior Manager Business Enablement 9224 2044 rhys.blakey@transport.nsw. gov.au

**Eric Gardner** Acting Crew Manager - Penrith 42893 Peric.gardner@transport.nsw.gov.au

Hana Farhat Readiness Project Coordinator 39435 & Hana.Farhat2@transport.nsw.gov.au

Andree Porter Operations - ROC 20113 Andree. Porter@transport.nsw.gov.au

**Toby Reynolds** Shift Manager Central 35982 Coby.reynolds@transport.nsw.gov.au

Kerrie-Ann Clarke Administration Support Campbelltown 61725 kerrie-ann.clarke@transport.nsw.gov.au



#### Matthew Quinn

Head of Crew Service Experience Sector 2

Solution Soluti Solution Solution Solution Solution Solution Solution S

#### Mario Chalouhi

Senior Manager Continuation Training & Competence 42616

Mario.Chalouhi@transport.nsw.gov.au

**Gurdip Singh** Standards Competency Officer

Solution State Not Sta

## Service Delivery Response

#### Megan Parker

Service Delivery Response 6 0491226502 7 megan.parker@transport.nsw.gov.au

### Leigh Lawton

Service Delivery Response Sold 0418237261 Pleigh.lawton@transport.nsw.gov.au

#### Maintenance

#### Fleet Maintenance

Hoshedar Movdawalla Fleet Maintenance Sydney Trains 2 0532 2 1274 HOSHEDAR.MOVDAWALLA@ transport.nsw.gov.au

#### Ram Ramaswamy

Fleet Maintenance Sydney Trains 2 0523 RAMYAVARAN.RAMASWAMY@ transport.nsw.gov.au

#### Network Maintenance

#### Zaneta Janevski

Engineering & Maintenance 87570199 2aneta.janevski@transport.nsw.gov.au

Shannon Newton Track Access Coordinator – North 95363791 Shannon.Newton@transport.nsw.gov. Xerxes Francia

Track Access Coordinator – North Hornsby Network Base 3 6740 Xerxes.Francia@transport.nsw.gov.au

Jonathan Barnes Track Access Coordinator – West Blacktown Network Base 87512

Donathan.Barnes@transport.nsw.gov.au

Ennio Soster SCE Project Delivery Electrical \$\sigma 25236 \vertice{25917} \$\vertice{\vertice{25236}} ENNIO.SOSTER@transport.nsw.gov.au

#### 

Adrian Aquilina Team leader - Strathfield Mains 97526610 & adrian.aquilina@transport.nsw.gov.au

Christina Morgan Administration Support ICON 9379 6051

Dristina.Morgan@transport.nsw.gov.au

WN 38 — 12 September 2022



#### Lorinda Melvin

Administration Support S 0439510480 Plorinda.melvin@transport.nsw.gov.au

#### **Edward Lusik**

Team Leader Signals CBD 95368135 & edward.lusik@transport.nsw.gov.au

#### **Major Works**

Greg Page Infrastructure Track → 25375 Ø gregory.page@transport.nsw.gov.au

#### **Michael Warner**

Signals and Electricity 9848 9333 Ø michael.warner@transport.nsw.gov.au

### **Logistics & Supply Chain**

Murari Singh Contract Assurance Administrator 02 9848 9698 Murari.Singh@transport.nsw.gov.au

## **Engineering & System Integrity**

Teresa Sitjar Signalling & Control Systems ↓ 42458 ☆ Teresa.Sitjar@transport.nsw.gov.au

#### Yass Zahab

Geotechnical Services 2 7589 Yassine.El-Zahab@transport.nsw.gov.au

#### **Richard Agostino**

C and CS 2 0875 9 2137 Richard.Agostino@transport.nsw.gov.au

#### Human Resources

#### Robert Neloski

Training — Learning and Development 2 7567 Probert.neloski@transport.nsw.gov.au

#### Peter Nilon

Survey Group

S 9848 9904

Deter.nilon@transport.nsw.gov.au

# Trainlink

Phillip Antoniolli Operational Improvement Manager 8574 2960 0417694249 Phillip.antoniolli@transport.nsw.gov.au

Ashley Brandse Associate Director Operations North & Central 4962 9820 ASHLEY.BRANDSE@transport.nsw.gov.au

#### **Robert Blanch**

Area Manager Hunter & Regional North

Section Se

#### Netti Byrnes

Area Manager Central Coast

Annette.Byrnes@transport.nsw.gov.au

WN 38 — 12 September 2022



Leisa Case Area Manager Central Intercity Annette.Byrnes@transport.nsw.gov.au

**Dwayne Purcell** Area Manager Central Regional 0428670580 Ð

DWAYNE.PURCELL@transport.nsw.gov.au

**Michael Dorrian** Area\_Manager South Coast S 0439743316 Michael.dorrian@transport.nsw.gov.au

#### Ian Modon

Area Manager South Main 0427016255







# **NOTICE TO SUBSCRIBERS**

The Weekly Notice is issued every Tuesday, and takes effect on the following Monday.

Those who require the Weekly Notice must ensure that they receive it and are aware of the changes that affect their work duties and responsibilities.

# **Director Network Standards, Systems & Quality**

## **Sydney Trains**

Burwood NSW 2134 Tuesday, 30 August 2022