

weekly notice



Monday, 15 January 2024

RailSafe

Sunday, 21 January 2024



See online for all Safeworking Information

www.railsafe.org.au

Safeworking information, including Weekly Notices and SAFE Notices, is available on the RailSafe website.

By accessing Weekly Notices and SAFE Notices online, you will receive safety information more quickly. Weekly Notices remain on the RailSafe website for two years; Permanent and Temporary SAFE Notices remain online as long as they are current.

Anyone needing back issues of Weekly Notices and SAFE Notices should contact the Network Rules unit.

If you are outside Sydney Trains, you can reach the RailSafe website via the following address:

www.railsafe.org.au

Other Safeworking documents, such as Network Rules, Network Procedures, Network Local Appendices, Safeworking Policies, SafeTracks flyers, and contractor information are also available online.

Director Safety and Standards Sydney Trains

Continued on next page

CONTENTS

PUBLICATION DEADLINES AND SUBMISSION OF ARTICLES	4
ARTC SOUTHERN SYDNEY FREIGHT LINE (SSFL): COMMISSIONING OF	_
THE NEW CROSSING LOOP AT WARWICK FARM (DIAGRAM)	5
STANMORE - PETERSHAM (CENTRAL INNER WEST) – CONVERSION OF	
SIGNALS TO LED TYPE	6
STATUS OF TOM NOTICES	7
STATUS OF PERMANENT SAFE NOTICES	9
STATUS OF NETWORK MANUALS AND FORMS	10
DISTRIBUTION OFFICERS	12



PUBLICATION DEADLINES AND SUBMISSION OF ARTICLES

Dates of the next four Weekly Notices and deadlines for articles are:

Weekly Notice	For Week	Deadline
5	22/01/2024 – 28/01/2024	02/01/2024
6	29/01/2024 - 04/02/2024	09/01/2024
7	05/02/2024 - 11/02/2024	16/01/2024

To meet printing and distributing schedules, articles for a Weekly Notice must be received by its deadline.

Articles submitted after a deadline will be published in the next issue of the Weekly Notice. This may result in information not being distributed in time for it to be acted upon.

When submitting articles, please include your name, position title, telephone numbers and email address at the end of the articles as shown below:

Steve Swanson

Network Rules SpecialistTel:02 8922 4183 (external)2 4183 (internal)Email:stephen.swanson@transport.nsw.gov.au



ARTC SOUTHERN SYDNEY FREIGHT LINE (SSFL): COMMISSIONING OF THE NEW CROSSING LOOP AT WARWICK FARM


Commencing at 0200 hours on **Saturday, 03 February 2024** and continuing until 0000 hours on Monday, 06 February 2024, the following work will be carried out:


- Commissioning of the new crossing loop at Warwick Farm, between Leightonfield and Glenfield.
- ARTC 240 and 241 crossovers are scheduled to be commissioned in this commissioning event.
- Updates to the Sydney Trains ATRICS to reflect these changes.
- See attached Drivers Diagram.

VER02122023

Adrian Magrath

Signalling Manager, Fulton Hogan Mobile: 0427 955 277 Email: Adrian.Magrath@fultonhogan.com.au







STANMORE - PETERSHAM (CENTRAL INNER WEST) – CONVERSION OF SIGNALS TO LED TYPE

Commencing at 0200 hours on **Saturday, 03 February 2024** and continuing until 0200 hours on Monday, 05 February 2024 the following work will be carried out:

The following Signals between Stanmore and Petersham will be upgraded to LED Type at the same location. The indications displayed by the Signal will not change.

- Up Suburban: S2.58, S2.74 & S3.22
- Down Main: M2.57 & M2.75.
- Up Main: M2.58, M2.74 & M3.22

VER20112023

Neil Hook

Commissioning Engineer Signalling Project Engineering & Maintenance, Sydney Trains Mob: 0423 363 577 Email: neil.hook@transport.nsw.gov.au

Mark Collier

Signal Design Engineer, Signalling & Control Systems, Engineering & System Integrity, Sydney Trains Tel: 02 8574 2641 Email: mark.collier@transport.nsw.gov.au



STATUS OF TOM NOTICES

018 - 2007 Emergency equipment boxes Rail 01/11/07 19/11/07 010 - 2012 48 Class: Train Operations Manual (TOM) 25/10/12 0/41/1/12 003 - 2013 48 Class: Wheels 07/02/13 10/02/13 0015 - 2013 OMET 200: Minimum Standards for Electric Trains 30/05/13 09/06/13 002 - 2014 OMET 220: Wheelsip light indications 20/02/14 02/03/14 004 - 2017 TWP 174 Lec Radio 20/07/17 31/07/17 018 - 2017 Amendment to OMET 200 14/12/17 24/12/17 015 - 2018 OMET 228 Control Circuit Failure 23/08/18 28/08/18 005 - 2018 OMET 226 Applying power from the rear 18/08/18 28/08/18 006 - 2018 OMET 226 Applying power from the rear 18/08/18 28/08/18 006 - 2018 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 003 - 2019 TWP 136 Defective whotomatic Train Protect	Number	Title	Issued	Effective
003 - 2013 48 Class: Wheels 07/02/13 10/02/13 015 - 2013 OMET 200: Minimum Standards for Electric Trains 30/05/13 09/06/13 002 - 2014 OMET 200: Wheelslip light indications 20/02/14 02/03/14 004 - 2016 OMET 220: Evaluere of Train Management System 14/07/16 24/07/16 004 - 2017 TWP 174 Ice Radio 20/07/17 31/07/17 018 - 2018 OMET 228 Control Circuit Failure 23/08/18 28/08/18 005 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 006 - 2018 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 192 Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 004 - 201	018 – 2007	Emergency equipment boxes Rail	01/11/07	19/11/07
015 - 2013 OMET 200: Minimum Standards for Electric Trains 30/05/13 09/06/13 002 - 2014 OMET 220: Wheelslip light indications 20/02/14 02/03/14 004 - 2016 OMET 262: Failure of Train Management System 14/07/16 24/07/16 004 - 2017 TWP 174 Ice Radio 20/07/17 31/07/17 018 - 2018 OMET 228 Control Circuit Failure 23/08/18 02/09/18 005 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 008 - 2018 NWP 154 Responding to incapacitated Driver/Guard 18/08/18 27/08/18 003 - 2019 TWP 1954 Responding to incapacitated Driver/Guard 18/08/18 27/08/18 003 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 004 - 2020 TWP 192 Abefective Automatic Brakes 20/05/20 08/06/20 005 - 2020 TWP 124 Defective Automatic Brakes 20/05/20 08/06/20 <td< td=""><td>010 – 2012</td><td>48 Class: Train Operations Manual (TOM)</td><td>25/10/12</td><td>04/11/12</td></td<>	010 – 2012	48 Class: Train Operations Manual (TOM)	25/10/12	04/11/12
002 - 2014 OMET 220: Wheelslip light indications 20/02/14 02/03/14 004 - 2016 OMET 262: Failure of Train Management System 14/07/16 24/07/16 004 - 2017 TWP 174 Ice Radio 20/07/17 31/07/17 018 - 2017 Amendment to OMET 200 14/12/17 24/12/17 012 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 0016 - 2018 Network Rules Operational standards update 17/08/18 27/08/18 003 - 2019 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 003 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 004 - 2019 TWP 118 Defective wheels 06/03/19 24/03/19 004 - 2020 TWP 118 Reporting Faults 11/04/19 24/03/19 004 - 2020 TWP 140 Defective Warkes 20/05/20 08/06/20 005 - 2020 TWP 162 Erfecti	003 – 2013	48 Class: Wheels	07/02/13	10/02/13
004 - 2016 OMET 262: Failure of Train Management System 14/07/16 24/07/16 004 - 2017 TWP 174 Ice Radio 20/07/17 31/07/17 018 - 2017 Amendment to OMET 200 14/12/17 24/12/17 012 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 006 - 2018 OMET 254 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 017 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 136 Defective a Rese 20/05/20 08/06/20 009 - 2019 TWP 130 Automatic Train Protection 06/03/19 24/03/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 012 - 2020 TWP 126	015 – 2013	OMET 200: Minimum Standards for Electric Trains	30/05/13	09/06/13
004 - 2017 TWP 174 Ice Radio 20/07/17 31/07/17 018 - 2017 Amendment to OMET 200 14/12/17 24/12/17 012 - 2018 OMET 228 Control Circuit Failure 23/08/18 02/09/18 005 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 006 - 2018 NEW 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 001 - 2018 Network Rules Operational standards update 17/08/18 27/08/18 003 - 2019 TWP 132 Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 130 Automatic Train Protection 06/03/19 24/03/19 004 - 2020 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 012 - 2020 TWP 126 Defective Automatic Brakes 20/07/20 <td>002 – 2014</td> <td>OMET 220: Wheelslip light indications</td> <td>20/02/14</td> <td>02/03/14</td>	002 – 2014	OMET 220: Wheelslip light indications	20/02/14	02/03/14
018 - 2017 Amendment to OMET 200 14/12/17 24/12/17 012 - 2018 OMET 228 Control Circuit Failure 23/08/18 02/09/18 005 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 008 - 2018 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 003 - 2019 OMET 254: Minimum Tractive Effort Requirements 21/02/19 03/03/19 003 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 009 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 004 - 2020 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogic Faults 20/05/20 08/06/20 013 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 014 - 2020 TWP 112 Changing ends 20/07	004 – 2016	OMET 262: Failure of Train Management System	14/07/16	24/07/16
012 - 2018 OMET 228 Control Circuit Failure 23/08/18 02/09/18 005 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 008 - 2018 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 003 - 2019 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 27/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 004 - 2019 TWP 130 Automatic Train Protection 06/03/19 24/03/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 011 - 2020 TWP 126 Defective Brakes 20/05/20 08/06/20 011 - 2020 TWP 126 Carrain Crew Bell Signals 02/06/20 15/06/20 011 - 2020 TWP 160 Driver	004 – 2017	TWP 174 Ice Radio	20/07/17	31/07/17
005 - 2018 OMET 242 Reverser handle jams in forward or reverse 18/08/18 28/08/18 006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 008 - 2018 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 016 - 2018 Network Rules Operational standards update 17/08/18 27/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 009 - 2019 Train crew relieved in service & relay driver 06/03/19 24/03/19 004 - 2020 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/07/20 08/06/20 014 - 2020 TWP 124 Defective Brakes 20/07/20 03/08/20 017 - 2020 WP 162 Train Crew Bell Signals 02/07/20 03/08/20 017 - 2020 TWP 160 Driver procedure	018 - 2017	Amendment to OMET 200	14/12/17	24/12/17
006 - 2018 OMET 250 Applying power from the rear 18/08/18 28/08/18 008 - 2018 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 016 - 2018 Network Rules Operational standards update 17/08/18 27/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 007 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 008 - 2019 TwP 190 Automatic Train Protection 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 124 Defective Automatic Brakes 20/05/20 08/06/20 011 - 2020 TWP 126 Drain Crew Bell Signals 02/06/20 15/06/20 011 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city unde	012 – 2018	OMET 228 Control Circuit Failure	23/08/18	02/09/18
008 - 2018 TWP 154 Responding to incapacitated Driver/Guard 18/08/18 28/08/18 016 - 2018 Network Rules Operational standards update 17/08/18 27/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 011 - 2020 TWP 112 Changing ends 20/05/20 08/06/20 011 - 2020 TWP 112 Changing ends 20/07/20 3/08/20 011 - 2020 TWP 116 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 TWP 112 Changing ends 20/07/20 3/08/20 011 - 2020 TWP 112 Changing ends 21/04/22 <t< td=""><td>005 – 2018</td><td>OMET 242 Reverser handle jams in forward or reverse</td><td>18/08/18</td><td>28/08/18</td></t<>	005 – 2018	OMET 242 Reverser handle jams in forward or reverse	18/08/18	28/08/18
016 - 2018 Network Rules Operational standards update 17/08/18 27/08/18 003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 196 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 011 - 2020 TWP 160 Criver procedure at stations 21/04/22 08/05/22 023 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 TWP 160 Driver procedure at station	006 – 2018	OMET 250 Applying power from the rear	18/08/18	28/08/18
003 - 2019 OMET 264: Minimum Tractive Effort Requirements 21/02/19 03/03/19 012 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 009 - 2019 Train crew relieved in service & relay driver 06/03/19 24/03/19 004 - 2019 TWP 136 Defective Wates 20/05/20 08/06/20 004 - 2019 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 124 Defective Automatic Brakes 20/05/20 08/06/20 011 - 2020 WR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 11/04/22 08/05/22 023 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Twe 160 Driver procedure at stations 21/04/22	008 – 2018	TWP 154 Responding to incapacitated Driver/Guard	18/08/18	28/08/18
012 - 2019 TWP 192: Working Trains Out of service 21/02/19 03/03/19 007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 009 - 2019 Train crew relieved in service & relay driver 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 011 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 011 - 2020 TWP 122 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 111 - 2021 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 023 - 2022 Twe 160 Driver procedure at stations 21/04/22 08/05/22 02/08/22	016 - 2018	Network Rules Operational standards update	17/08/18	27/08/18
007 - 2019 TWP 136 Defective wheels 06/03/19 24/03/19 008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 009 - 2019 Train crew relieved in service & relay driver 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 011 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with of/12/20 07/12/20 14/12/20 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 TWP 150: Damaged or Missing Window Gla	003 - 2019	OMET 264: Minimum Tractive Effort Requirements	21/02/19	03/03/19
008 - 2019 TWP 190 Automatic Train Protection 06/03/19 24/03/19 009 - 2019 Train crew relieved in service & relay driver 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 112 Changing ends 02/06/20 15/06/20 011 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023<	012 – 2019	TWP 192: Working Trains Out of service	21/02/19	03/03/19
009 - 2019 Train crew relieved in service & relay driver 06/03/19 24/03/19 004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 014 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 027 - 2022 </td <td>007 – 2019</td> <td>TWP 136 Defective wheels</td> <td>06/03/19</td> <td>24/03/19</td>	007 – 2019	TWP 136 Defective wheels	06/03/19	24/03/19
004 - 2019 TWP 118 Reporting Faults 11/04/19 28/04/19 004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 014 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 Testing of Tangara Sets fitted with European Train 08/12/22 16/12/22 027 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on 20/02/23 05/03/23	008 – 2019	TWP 190 Automatic Train Protection	06/03/19	24/03/19
004 - 2020 TWP 124 Defective Brakes 20/05/20 08/06/20 005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 014 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 Testing of Tangara Sets fitted with European Train 08/12/22 16/12/22 027 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on 20/02/23 05/03/23 016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 <t< td=""><td>009 – 2019</td><td>Train crew relieved in service & relay driver</td><td>06/03/19</td><td>24/03/19</td></t<>	009 – 2019	Train crew relieved in service & relay driver	06/03/19	24/03/19
005 - 2020 TWP 126 Defective Automatic Brakes 20/05/20 08/06/20 012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 014 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 Testing of Tangara Sets fitted with European Train 08/12/22 16/12/22 027 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on 20/03/23 05/03/23 016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 20/03/23 017 - 2023 TWP 138 Assisting Trains using Emergency Couplers <td< td=""><td>004 – 2019</td><td>TWP 118 Reporting Faults</td><td>11/04/19</td><td>28/04/19</td></td<>	004 – 2019	TWP 118 Reporting Faults	11/04/19	28/04/19
012 - 2020 WAR 202 Bogie Faults 20/05/20 08/06/20 011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 014 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with 07/12/20 14/12/20 deflated air springs in the city underground 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 Testing of Tangara Sets fitted with European Train 08/12/22 16/12/22 027 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on 20/03/23 05/03/23 016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 20/03/23 017 - 2023 TWP 138 Assisting Trains using Emergency Couplers 07/03/23 20/03/23 022 - 2023 WB Radios on Waratah, Oscar, Millenium, Tangara and	004 - 2020	TWP 124 Defective Brakes	20/05/20	08/06/20
011 - 2020 TWP 162 Train Crew Bell Signals 02/06/20 15/06/20 014 - 2020 TWP 112 Changing ends 20/07/20 03/08/20 017 - 2020 Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground 07/12/20 14/12/20 011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 Testing of Tangara Sets fitted with European Train signalling) equipment at Mortdale Maintenance Centre 08/12/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on Millennium trains 20/02/23 05/03/23 016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 017 - 2023 TWP 138 Assisting Trains using Emergency Couplers 07/03/23 20/03/23 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23	005 - 2020	TWP 126 Defective Automatic Brakes	20/05/20	08/06/20
014 - 2020TWP 112 Changing ends20/07/2003/08/20017 - 2020Operating Tangara, OSCAR, Millenium and Waratah with07/12/2014/12/20deflated air springs in the city underground011 - 2021Exception to OMET 200 & 35017/11/2129/11/21005 - 2022TWP 160 Driver procedure at stations21/04/2208/05/22023 - 202208/05/22023 - 2022Exception to OMET 254 Topside Preparation Locations16/08/2222/08/22028 - 2022Testing of Tangara Sets fitted with European Train signalling) equipment at Mortdale Maintenance Centre08/12/2216/12/22027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/2201/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains07/03/2320/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection (ATP) equipment19/06/2326/06/23	012 - 2020	WAR 202 Bogie Faults	20/05/20	08/06/20
017 - 2020Operating Tangara, OSCAR, Millenium and Waratah with deflated air springs in the city underground07/12/2014/12/20011 - 2021Exception to OMET 200 & 35017/11/2129/11/21005 - 2022TWP 160 Driver procedure at stations21/04/2208/05/22023 - 2022Exception to OMET 254 Topside Preparation Locations16/08/2222/08/22028 - 2022Testing of Tangara Sets fitted with European Train Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre08/12/2210/10/22027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/2201/0/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains07/03/2320/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23023 - 2023OSCAR trains fitted with Automatic Train Protection (ATP) equipment19/06/2326/06/23	011 - 2020	TWP 162 Train Crew Bell Signals	02/06/20	15/06/20
deflated air springs in the city underground011 - 2021Exception to OMET 200 & 35017/11/2129/11/21005 - 2022TWP 160 Driver procedure at stations21/04/2208/05/22023 - 2022Exception to OMET 254 Topside Preparation Locations16/08/2222/08/22028 - 2022Testing of Tangara Sets fitted with European Train Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre08/12/2210/10/22027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains20/02/2305/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2323/04/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23	014 - 2020	TWP 112 Changing ends	20/07/20	03/08/20
011 - 2021 Exception to OMET 200 & 350 17/11/21 29/11/21 005 - 2022 TWP 160 Driver procedure at stations 21/04/22 08/05/22 023 - 2022 Exception to OMET 254 Topside Preparation Locations 16/08/22 22/08/22 028 - 2022 Testing of Tangara Sets fitted with European Train 08/12/22 16/12/22 028 - 2022 Testing of Tangara Sets fitted with European Train 08/12/22 16/12/22 Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre 027 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on 20/02/23 05/03/23 016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 017 - 2023 TWP 138 Assisting Trains using Emergency Couplers 07/03/23 20/03/23 022 - 2023 WB Radios on Waratah, Oscar, Millenium, Tangara and K 05/04/23 23/04/23 sets 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23	017 - 2020	Operating Tangara, OSCAR, Millenium and Waratah with	07/12/20	14/12/20
005 - 2022TWP 160 Driver procedure at stations21/04/2208/05/22023 - 2022Exception to OMET 254 Topside Preparation Locations16/08/2222/08/22028 - 2022Testing of Tangara Sets fitted with European Train Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre08/12/2216/12/22027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains07/03/2320/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23		deflated air springs in the city underground		
023 - 2022Exception to OMET 254 Topside Preparation Locations16/08/2222/08/22028 - 2022Testing of Tangara Sets fitted with European Train Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre08/12/2216/12/22027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains20/02/2305/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection (ATP) equipment19/06/2326/06/23	011 - 2021	Exception to OMET 200 & 350	17/11/21	29/11/21
028 - 2022Testing of Tangara Sets fitted with European Train Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre08/12/2216/12/22027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains20/02/2305/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23	005 - 2022	TWP 160 Driver procedure at stations	21/04/22	08/05/22
Control System (ETCS) Level 1 & Level 2 (In cab signalling) equipment at Mortdale Maintenance Centre027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains20/02/2305/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23	023 - 2022	Exception to OMET 254 Topside Preparation Locations	16/08/22	22/08/22
signalling) equipment at Mortdale Maintenance Centre027 - 2022TWP 150: Damaged or Missing Window Glass27/09/2210/10/22014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains20/02/2305/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection (ATP) equipment19/06/2326/06/23	028 - 2022	Testing of Tangara Sets fitted with European Train	08/12/22	16/12/22
027 - 2022 TWP 150: Damaged or Missing Window Glass 27/09/22 10/10/22 014 - 2023 Use of Automatic Train Protection (ATP) equipment on Millennium trains 20/02/23 05/03/23 016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 017 - 2023 TWP 138 Assisting Trains using Emergency Couplers 07/03/23 20/03/23 022 - 2023 WB Radios on Waratah, Oscar, Millenium, Tangara and K 05/04/23 23/04/23 sets 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23		Control System (ETCS) Level 1 & Level 2 (In cab		
014 - 2023Use of Automatic Train Protection (ATP) equipment on Millennium trains20/02/2305/03/23016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23(ATP) equipment19/06/2326/06/23		signalling) equipment at Mortdale Maintenance Centre		
Millennium trains016 - 2023TWP 152 Disabled trains07/03/2320/03/23017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23sets023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23(ATP) equipment19/06/2326/06/2326/06/23	027 - 2022	TWP 150: Damaged or Missing Window Glass	27/09/22	10/10/22
016 - 2023 TWP 152 Disabled trains 07/03/23 20/03/23 017 - 2023 TWP 138 Assisting Trains using Emergency Couplers 07/03/23 20/03/23 022 - 2023 WB Radios on Waratah, Oscar, Millenium, Tangara and K 05/04/23 23/04/23 sets 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23	014 - 2023	Use of Automatic Train Protection (ATP) equipment on	20/02/23	05/03/23
017 - 2023TWP 138 Assisting Trains using Emergency Couplers07/03/2320/03/23022 - 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23sets023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23(ATP) equipment19/06/2326/06/2326/06/23		Millennium trains		
022 – 2023WB Radios on Waratah, Oscar, Millenium, Tangara and K05/04/2323/04/23sets023 - 2023OSCAR trains fitted with Automatic Train Protection19/06/2326/06/23(ATP) equipment	016 - 2023	TWP 152 Disabled trains	07/03/23	20/03/23
sets 023 - 2023 OSCAR trains fitted with Automatic Train Protection 19/06/23 26/06/23 (ATP) equipment	017 - 2023	TWP 138 Assisting Trains using Emergency Couplers	07/03/23	20/03/23
(ATP) equipment	022 – 2023	5	05/04/23	23/04/23
	023 - 2023		19/06/23	26/06/23
	028 – 2023		07/08/23	21/08/23

WN 4 — 15 January 2024



Number	Title	Issued	Effective
029 - 2023	Testing of an OSCAR Set (H5) with ETCS Level 2 equipment	01/09/23	04/09/23
026 – 2023	TWP 156: Operating doors	15/09/23	25/09/23
032 - 2023	TWP 100 Responsibilities of Train Crews	19/09/23	30/09/23
030 - 2023	Tangara Automatic Train Protection (ATP) odometry testing	26/09/23	03/10/23
031 - 2023	Operation of Tangara trains fitted with ATP with Automatic Train Protection (ATP)	10/10/23	16/10/23
033 - 2023	Waratah (A and B SET) trains fitted with Automatic Train Protect equipment	17/10/23	23/10/23
034 - 2023	Testing Tangara trains fitted with ETCS Level 2	02/11/23	03/11/23



STATUS OF PERMANENT SAFE NOTICES

Number	Title	Issued	Effective
001 - 2023	Use of Signal Key Switches	19/01/23	25/01/23
002 - 2023	Control of the Country Rail Network (CRN) by UGL Regional Linx (UGLRL)	16/02/23	28/02/23
003 - 2023	New Trackside Signage associated with Digital Systems Train Testing	03/02/23	25/02/23

Steve Swanson

Network Rules Specialist

- Tel: 02 8922 4183 (external) 2 4183 (internal)
- Email: stephen.swanson@transport.nsw.gov.au



STATUS OF NETWORK MANUALS AND FORMS

Network Manuals

Network Local Appendices	RailSafe Website	Online documents
Operator Specific Procedures	RailSafe Website	Online documents
Network Rules	RailSafe Website	Online documents
Network Procedures	RailSafe Website	Online documents
Forms	RailSafe Website	Online documents (or order as applicable)



weekly notice

Title

Status Sheet

Date issued

Train Working Procedures

TWP 100	TN 006 - 2021	April 2021
TWP 102	3	May 2012
TWP 108	4	May 2012
TWP 110	TN 009 - 2019	March 2019
TWP 112	TN 014 - 2020	August 2020
TWP 114	4	November 2015
TWP 116	3	May 2012
TWP 118	TN 004 - 2019	April 2019
TWP 120	3	May 2012
TWP 122	3	May 2012
TWP 124	TN 004 - 2020	May 2019
TWP 126	TN 005 - 2020	May 2019
TWP 128	3	May 2012
TWP 130	3	May 2012
TWP 132	3	May 2012
TWP 134	3	May 2012
TWP 136	TN 007 - 2019	March 2019
TWP 138	TN 017 - 2023	March 2023
TWP 142	3	May 2012
TWP 144	5	May 2012
TWP 146	3	May 2012
TWP 148	3	May 2012
TWP 150	TN 005 - 2017	April 2017
TWP 152	TN 016 - 2023	March 2023
TWP 154	TN 008 - 2018	July 2018
TWP 156	TN 011 - 2019	March 2019
TWP 158	3	May 2012
TWP 160	TN 005 - 2022	May 2022
TWP 162	TN 011- 2020	May 2019
TWP 164	4	May 2012
TWP 166	3	May 2012
TWP 168	3	May 2012
TWP 170	3	May 2012
TWP 172	4	May 2012
TWP 174	TN 004 - 2017	July 2017
TWP 176	TN 008 - 2017	July 2017
TWP 182	1	November 2015
TWP 188	1	November 2015
TWP 190	TN 008 - 2019	March 2019
TWP 192	TN 012 - 2019	March 2019



DISTRIBUTION OFFICERS

Sydney Trains

Safety and Environment

Maria Economou

Safety Support 2 4502 Maria.Economou@transport.nsw.gov.au

Train Crew Operations

Manager Day of Operations

8577 7029

於 TCOManagerDayofOperations@transport. nsw.gov.au

Train Crewing Tim Kelly Operating Standards Officer

Dimothy.kelly@transport.nsw.gov.au

Service Delivery Response

Megan Parker

Service Delivery Response 0491226502 megan.parker@transport.nsw.gov.au

Leigh Lawton

Service Delivery Response 0418237261 Pleigh.lawton@transport.nsw.gov.au

Maintenance

Fleet Maintenance

Hoshedar Movdawalla Fleet Maintenance Sydney Trains 2 0532 2 1274 HOSHEDAR.MOVDAWALLA@ transport.nsw.gov.au

WN 4 — 15 January 2024

Ram Ramaswamy

Fleet Maintenance Sydney Trains

Network Maintenance

Zaneta Janevski

Engineering & Maintenance 87570199 Zaneta.janevski@transport.nsw.gov.au

Shannon Newton

Track Access Coordinator – North 95363791 Shannon.Newton@transport.nsw.gov.

Bradley Stewart

Territory Planning Manager - Central Coast/Hamilton

Ennio Soster

SCE Project Delivery Electrical \$\sigma 25236 \vertic{1}{25917} \$\vee\$ ENNIO.SOSTER@transport.nsw.gov.au

Daljit Kaur Infrastructure Maintenance — Facilities 2 5922 2 5950 Daljit.Kaur@transport.nsw.gov.au

Adrian Aquilina Team leader - Strathfield Mains 97526610 adrian.aquilina@transport.nsw.gov.au



weekly notice

Christina Morgan

Administration Support ICON 9379 6051 & Christina.Morgan@transport.nsw.gov.au

Lorinda Melvin

Administration Support Sold 0439510480 Plorinda.melvin@transport.nsw.gov.au

Edward Lusik Team Leader Signals CBD № 95368135 & edward.lusik@transport.nsw.gov.au

Major Works

Greg Page Infrastructure Track → 25375 & gregory.page@transport.nsw.gov.au

Michael Warner Signals and Electricity ♦ 9848 9333 Ø michael.warner@transport.nsw.gov.au

Logistics & Supply Chain

Murari Singh Contract Assurance Administrator 02 9848 9698 Durari.Singh@transport.nsw.gov.au

Engineering & System Integrity

Yass Zahab

Geotechnical Services 2 7589 2 7786 Yassine.El-Zahab@transport.nsw.gov.au

Richard Agostino

C and CS 2 0875 Richard.Agostino@transport.nsw.gov.au

Human Resources

Robert Neloski Training — Learning and Development 2 7567 Probert.neloski@transport.nsw.gov.au

Trainlink

Phillip Antoniolli Operational Improvement Manager 8574 2960 0417694249 Phillip.antoniolli@transport.nsw.gov.au

Ashley Brandse Associate Director Operations North & Central 4962 9820 ASHLEY.BRANDSE@transport.nsw.gov.au

Robert Blanch

Area Manager Hunter & Regional North

Section Secti

WN 4 — 15 January 2024



Netti Byrnes

Area Manager Central Coast 43499210 0458261501 Annette.Byrnes@transport.nsw.gov.au

Leisa Case

Area Manager Central Intercity S I 0429900371 Annette.Byrnes@transport.nsw.gov.au

Dwayne Purcell Area Manager Central Regional 0428670580 DWAYNE.PURCELL@transport.nsw.gov.au

Michael Dorrian

Area Manager South Coast

S 0439743316

Dichael.dorrian@transport.nsw.gov.au

lan Modon

Area Manager South Main





NOTICE TO SUBSCRIBERS

The Weekly Notice is issued every Tuesday, and takes effect on the following Monday.

Those who require the Weekly Notice must ensure that they receive it and are aware of the changes that affect their work duties and responsibilities.

Director Network Standards, Systems & Quality

Sydney Trains

Level 4, 36-46 George Street Burwood NSW 2134 Tuesday, 19 December 2024