

SAFE Notice *2021* 1002

Telegram

SYDNEY

17 MARCH

0800 HOURS

TO:

SYDNEY TRAINS

Deputy Executive Director Network
Operations
Head of Service Delivery
Area Operations Managers Signal Box
Operations
Duty Control Manager ROC
Signal Box Operations
Deputy Executive Directors Train Crew
Crew Managers Train Crew
Shift Managers Train Crew

NSW TRAINS

Associate Director Network Coordination
Principal Manager Centralised Station & Crew
Support
Standards Officers Centralised Station & Crew
Support

STRUKTON LINE BLOCKAGE SYSTEM (LBS) PILOT TESTING

Effective from 0001hours, **Thursday, 18 March 2021**, this SAFE Notice Telegram details the requirements for testing of the Strukton Line Blockage System (LBS) on the network.

The Strukton LBS will be tested at various locations throughout network and the instructions below set out the requirements that must be in place for testing to be conducted.

- An authorised Signalling Representative must be provided in each case to perform the testing of the device using NSG 616 Precautions during signal equipment testing
- The Signalling Representative must coordinate the activation and of the LBS system with the appropriate Signaller
- A Qualified worker must be provided at the protecting signal to observe signal operation and must advise the Signalling Representative of aspects displayed during each test case and on completion of the testing
- Appropriate Worksite Protection must be in place as required at all times.

SYDNEY, 17 MARCH 2021

DIRECTOR SAFETY AND STANDARDS SYDNEY TRAINS

Returned to Controlling Manager: Date: Signed:



(Cut along this line and forward the detached receipt to your Controlling Manager)

To Controlling Manager:.....

Received SAFE Notice No. 1002 – 2021 Date:..... Signed:

Name (print): Location:

(Controlling Manager to retain this Acknowledgement of Receipt of the SAFE Notice for record purposes for 90 days)