Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions				
				Airport	Line						
NOTE: When working within Yard Limits, Rail Traffic may approach from any direction. LOOKOUT WORKING AROUND PLATFORMS Lookout working on tracks adjacent to platforms may only be permitted when; • A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or • A safe place can be created, for example, implementing ASB or a higher											
		form	of prot	tection o	on an adjace	nt line.					
Airport Line Tunnel 000.378 000.390 Up Airport line Handrail on bridge damaged and loose near 635A points No Safe Place Lookout Working prohibited											
Airport Line	Tunnel	000.660	010.500	All tracks	Tunnel	Warning system in the tunnel.	Do not enter the tunnel.				

	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Bankstov	wn Line		
NOTE	: When w	orking w	ithin Ya	ard Limit	ts, Rail Traf	fic may approach	from any
		.		direct	•	7 11	
Const	ruction we	orks ass	ociated	with the	e Sydney M	etro Project may	impact on
						assessment is es	•
						s and Procedures	
		•					
Looko		LOOKO	UT WO	RKING A	AROUND PL	ATFORMS	
	ut working	LOOKO g on trac	UT WO	RKING A	AROUND PL	ATFORMS ay only be permi	tted when;
	ut working e place car	LOOKO g on trac n easily l	UT WO ks adja be reac	RKING A cent to p hed (clin	AROUND PL platforms m nbing onto	ATFORMS ay only be permior under a platfor	tted when; rm from the
• A safe	ut working place car track mu	LOOKO g on trac n easily l st not be	UT WO ks adja be reac consid	RKING A cent to p hed (clin dered an	AROUND PL platforms m nbing onto d easily rea	ATFORMS ay only be permior under a platforched safe place)	tted when; rm from the , or
• A safe	ut working place car track mu	LOOKO g on trac n easily l st not be n be crea	UT WO ks adja be reacle considented, for	RKING A cent to p hed (clin dered an exampl	AROUND PL platforms m nbing onto d easily rea e, implemen	ATFORMS ay only be perminer under a platform the control of the co	tted when; rm from the , or
• A safe	ut working place car track mu	LOOKO g on trac n easily l st not be n be crea	UT WO ks adja be reacle considented, for	RKING A cent to p hed (clin dered an exampl	AROUND PL platforms m nbing onto d easily rea	ATFORMS ay only be perminer under a platform the control of the co	tted when; rm from the , or
• A safe	ut working place car track mu place car	LOOKO g on trac n easily l st not be n be crea	UT WO ks adja be reac e consid ted, for protecti	RKING Acent to place	AROUND PL platforms m nbing onto d easily rea e, implement n adjacent li	ATFORMS ay only be permitor under a platform the ched safe place) atting ASB or a highine.	tted when; rm from the , or gher form of
• A safe	ut working place car track mu	LOOKO g on trac n easily l st not be n be crea	UT WO ks adja be reacle considented, for	RKING A cent to p hed (clin dered an exampl	AROUND PL platforms m nbing onto d easily rea e, implemen	ATFORMS ay only be perminer under a platform the control of the co	tted when; rm from the , or

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Bankstown Line	Dulwich Hill- Hurlstone Park	007.783	007.960	Both lines	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Bankstown Line	Dulwich Hill- Hurlstone Park	008.103	008.594	Up Bankstown line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Bankstown Line	Dulwich Hill- Hurlstone Park	008.295	010.266	Down Bankstown line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Bankstown Line	Canterbury- Campsie	009.817	010.266	Up Bankstown line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Bankstown Line	Campsie- Belmore	011.792	012.116	Both lines	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Bankstown Line	Punchbowl- Bankstown	016.350	016.650	Both lines	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited

Issued 10 January 2024 Review Date 10 January 2025

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Chullora Br	ranch		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions					
	City Circle											
Looko	ut working place car track mu	LOOKO g on trac n easily k st not be n be crea	UT WOR ks adjace be reach consider ted, for	direct RKING A cent to p ned (clin lered an exampl	tion. AROUND PL platforms m nbing onto o d easily rea	ay only be permior under a platforched safe place) nting ASB or a hi	tted when; m from the , or					
City Circle	City Circle Tunnels	000.000	005.892	All tracks	Insufficient Sighting and Limited Clearance	Lookout Working prohibited in platform areas.	Lookout Working is not permitted in platform areas within the City Circle.					

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Cronulla L	ine		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Cronulla Line	Sutherland	024.969	025.568	Down line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Cronulla Line	Miranda	031.348	031.580	Down line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Cronulla Line	Caringbah	031.348	031.588	Up line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Cronulla Line	Caringbah	033.476	034.100	Down line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited
Cronulla Line	Woolooware	033.476	034.100	Up line	Insufficient Sighting and Limited Clearance	Insufficient sighting distance and no safe place can be accessed	Lookout Working Prohibited

Torking with the	ard Limits, Rail Trat	ne may approac	an monn any an	ection			
Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				East Hills I	Line		
Lookou	ıt working place car	LOOKO g on trac n easily	UT WO ks adja be reac	direction RKING AF Incent to plot to hed (climb	on. ROUND PL atforms m oing onto o	ATFORMS ay only be permor under a platfo	itted when; orm from the
• A safe		be crea	ated, for	example	•	ched safe place iting ASB or a h ne.	

Issued 10 January 2024 Review Date 10 January 2025

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Eastern Subu	rbs Line		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Issued 10 January 2024 Review Date 10 January 2025

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Flemington (Goods		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Illawarra	Line		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

All Lines Between Oatley at 018.371kms to Sutherland at 024.067kms, then Waterfall at 039.230kms to Unanderra at 088.593 are Bi-Directional. Unanderra to Bomaderry (Nowra) terminations and Unanderra to Lysaghts (Allans Creek Triangle line) is Single Line.

Construction works associated with the Sydney Metro Project may impact on safe places and sighting distances. An onsite risk assessment is essential to ensure compliance with the Network Rules and Procedures.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Illawarra Line		001.200	001.401	UP Illawarra Local	Hit by Train	No safe place in platform	Inadequate sighting distance. Lookout Working not permitted.
Illawarra Line		001.200	001.467	Down Illawarra Local	Hit by Train	No safe place in platform, inadequate sighting distance	Inadequate sighting distance. Lookout Working not permitted.
Illawarra Line		002.263	002.293	Down Illawarra Local	Hit by Train	Inadequate sighting distance	Inadequate sighting distance for required move time. Lookout Working not
Illawarra Line		002.766	002.800	UP Illawarra Local	Hit by Train	No safe place in platform, inadequate sighting distance	Lookout Working not
Illawarra Line		002.780	002.800	Down Illawarra Local	Hit by Train	No safe place in platform	Lookout Working not permitted.
Illawarra Line		003.012	003.920	Down Local Up Main	Hit by Train	Hit by Train	Inadequate sighting distance. Lookout Working not
Illawarra Line	Tempe	006.550	006.933	All lines	Hit by Train	Inadequate Sighting and No Safe Place	Lookout working not permitted
Illawarra Line		006.997	007.092	Up & Down Illawarra Main	Hit by Train	No Safe Place	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Illawarra Line		007.707	007.800	Down Illawarra Main	Hit by Train	No Safe Place	Lookout working not permitted
Illawarra Line		007.940	008.540	Up Local	Hit by Train	Inadequate Sighting and No Safe Place	Lookout working not permitted
Illawarra Line		007.991	008.085	Down Illawarra Main	Hit by Train	No Safe Place	Lookout working not permitted
Illawarra Line		012.300	012.600	Down Illawarra Main	Hit by Train	Inadequate Sighting and No Safe Place	permitted
Illawarra Line		013.200	013.600	UP Illawarra Local and Down Illawarra Main	Hit by Train	Inadequate Sighting and No Safe Place	Lookout working not permitted
Illawarra Line	Allawah to Hurstville	013.754	015.064	Down Main	Hit by Train	Inadequate Sighting and No Safe Place	Lookout working not permitted
Illawarra Line	Hurstville	014.255	014.698	Up Main Up Local Down Local	Hit by Train	Inadequate Sighting and No Safe Place	Lookout working not permitted
Illawarra Line	Penshurst	016.000	019.246	Down Illawarra Up Illawarra	Hit by Train	Inadequate Sighting and No Safe Place	Lookout working not permitted
Illawarra Line	Heathcote	035.468	035.794	Both	No Safe Place	Struck by Train	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Illawarra Line	Waterfall	041.186	041.461	Both	No Safe Place	Struck by Train	Lookout working not permitted
Illawarra Line		046.400	052.630	Both	No Safe Place	No refuges in cuttings.	Lookout working not permitted
Illawarra Line		047.210	047.475	Both	No Safe Place	Struck by Train	Lookout working not permitted
Illawarra Line		052.630	055.950	Down Main	No Safe Place	No refuges in cuttings.	Lookout working not permitted
Illawarra Line		055.950	058.750	Both	No Safe Place	No refuges in cuttings.	Lookout working not permitted

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Main North	Line		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

UP & DOWN Main Lines Between Cowan at 049.961kms and Hawkesbury River at 057.062kms, are Bi-Directional.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Main North Line	Strathfield Rail Underpass	012.655	013.720	Up Relief line	No Safe Place	No Safe Place	Lookout working not permitted
Main North Line	Mt Kuring-Gai to Berowra	043.860	044.020	Up Main North line	No Safe Place	No safe place due to the Cutting	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main North Line	Mt Kuring-Gai to Berowra	043.860	044.724	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Berowra	045.840	046.120	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Cowan	048.230	048.380	Up & Down Mai North lines, Up Refuge Loop	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Cowan	048.970	049.100	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Cowan	049.190	049.410	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Cowan	049.600	049.720	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Cowan	049.800	050.110	Up Main North line	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Boronia	050.110	050.310	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main North Line	Boronia	050.625	050.750	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Boronia	051.120	051.200	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Boronia	051.590	051.690	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Boronia	052.340	052.445	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Boronia	054.184	054.244	Up Main North line	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Hawkesbury River	054.274	054.330	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Hawkesbury River	054.475	054.510	Both Lines	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Hawkesbury River	054.510	054.700	Up Main Noth line	No Safe Place	Insufficient sighting distance and no safe place can be accessed	Lookout working not permitted
Main North Line	Hawkesbury River	055.170	055.443	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main North Line	Hawkesbury River	055.690	055.790	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Hawkesbury River	056.120	056.170	Up Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Hawkesbury River	056.330	056.770	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Hawkesbury River	056.980	057.050	Up Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Wondabyne	060.000	060.180	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Wondabyne	064.000	064.260	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Wondabyne	064.850	065.078	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Wondabyne	065.320	065.510	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Wondabyne	065.690	065.791	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Wondabyne	066.085	066.225	Both lines	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Woy Woy	066.400	066.940	Up Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted
Main North Line	Woy Woy	066.400	067.058	Down Main North line	No Safe Place	Insufficient sighting distance and no safe place can be	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main North Line	Woy Woy - Parks Bay Underbridge	073.528	073.603	Both	No Safe Place	No Safe Place	Lookout working not permitted
Main North Line	Tascott	076.962	077.169	Both	Cutting	No Safe Place due to cutting	Lookout working not permitted
Main North Line	Ourimbah Creek Bridge	096.831	096.909	Both	No Safe Place	No Safe Place	Lookout working not permitted
Main North Line	Ourimbah Creek Bridge	096.831	096.909	Both	No Safe Place	No Safe Place	Lookout working not permitted
Main North Line	Dora Creek Underbridge and Station Platforms	126.990	127.325	Both	No Safe Place	No Safe Place on bridge (no refuges) and No Safe Place between platforms	Lookout working not permitted
Main North Line	Sulphide Junction Signal S123	152.280	152.280	Not Indicated	Safeworking	S123 signal overlap distance for a caution indication is 1592 metres compared to the signals in the rear that have an overlap distance of over 2000 metres for a caution indication.	It is not recommended that S123 signal be used for worksite protection.

Issued 10 January 2024 Review Date 10 January 2025

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions		
				Main South	Line				
NOTE	: When w			directi	on.	ic may approac	h from any		
• A safe	LOOKOUT WORKING AROUND PLATFORMS Lookout working on tracks adjacent to platforms may only be permitted when; • A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or • A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.								
Main South	Villawood	023.880	024.400	Up Main	Struck by Train	Insufficient sighting distance	e Lookout working not		

Main South Line	Villawood	023.880	024.400	Up Main South line	Struck by Train	Insufficient sighting distance	Lookout working not permitted
Main South Line	Villawood	024.400	024.820	Down Main South line	Struck by Train	Insufficient sighting distance	Lookout working not permitted
Main South Line	Canley Vale	027.283	027.700	Up Main South line	Struck by Train	Insufficient sighting distance	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Main Subur	ban Line		
Lookou • A safe	ıt working place car track mus	LOOKO Jon trac n easily lest not be to be crea	UT WOks adjace reace considered, for ordecti	direct RKING A cent to p hed (clim dered and example	ion. ROUND PL platforms manbing onto d d easily read	ay only be permi or under a platfo ched safe place) iting ASB or a hi	tted when; rm from the , or
Main Suburban Line		000.470	000.605	Up Local	Hand rail on bridge loose and unsafe as a barricade or fall restraint.No Safe Place	10 metre fall if hand rail collapses, Struck by Train	Lookout working not permitted
Main Suburban Line		006.323	006.346	Down Suburban Up Suburban	No Safe Place	Struck by Train	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main Suburban Line		006.472	006.589	Down Suburban Up Suburban	No Safe Place	Struck by Train	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Main Wes	t Line		
NOTE	: When w	orking w	ithin Ya	ard Limits directi	•	ic may approac	h from any
All Line	es Betwee			Direction		, Zag at 150.755 ATFORMS	kms are Bi-
• A safe	place car track mu	g on trac n easily l st not be	ks adja pe reac e consid	cent to p hed (clim dered and	latforms model bing onto deleter to the latest terms on the latest terms of the latest	ay only be perm or under a platfo ched safe place	orm from the), or
• A Saie	piace car		·	•	e, impiemer adjacent li	iting ASB or a h ne.	igner form of
Main West Line		023.410	023.460	Up Main Down Main	No Safe Place	Struck by Train	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main West Line		023.624	023.647	Up Main Down Main Up Suburban Down Suburban	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		023.806	023.826	Up Main Down Main Up Suburban Down Suburban	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		023.987	024.018	Up Main Down Main Up Suburban Down Suburban	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		033.033	034.080	Up Main	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		063.145	063.354	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		063.414	063.485	Both	No Safe Place	Struck by Train	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main West Line		064.665	064.756	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		067.337	067.476	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		068.919	069.102	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		069.224	069.520	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		087.640	087.831	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		089.484	089.680	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		089.977	090.260	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		091.350	091.647	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		099.363	099.462	Both	No Safe Place	Struck by Train	Lookout working not permitted

Last Updated 10 January 2024

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

_	-		•				
Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Main West Line		111.137	111.447	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		113.041	113.272	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line		122.157	122.501	Both	No Safe Place	Struck by Train	Lookout working not permitted
Main West Line	Zig Zag Tunnel	145.168	150.937	Both lines	No Safe Place	Zig Zag tunnel has no safe place	Lookout working not permitted
Main West Line		155.691	155.870	Both	No Safe Place	Lithgow Station Platform - No Safe Place in this section of the corridor	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Metropolitan	Goods		
Looko • A safe	ut working e place car track mus	LOOKC on trac easily st not b be crea	OUT WO cks adja be reac e consid ated, for	directi RKING AI cent to pl hed (clim dered and example	on. ROUND P latforms r bing onto I easily re	LATFORMS nay only be permi or under a platfor ached safe place) enting ASB or a high line.	tted when; rm from the , or
Metropolitan Goods	ARTC/Transport for NSW Shared Corridor	021.693	022.307	Sefton West Fork - UP and Down Goods	Worksite Protection	Additional requirements for Lookout Working within Danger Zone in ARTC/Transport for NSW shared corridor	Work in the Danger Zone using the Lookout Working method MUST be done in daylight hours only, for a maximum of two

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				North Sh	ore		

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction. Construction works associated with the Sydney Metro Project may impact on safe places and sighting distances. An onsite risk assessment is essential to ensure compliance with the Network Rules and Procedures LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

North Shore	Waverton	006.466	007.453	Up	No Safe Place	UP MN Insufficient safe place	Lookout working not permitted
North Shore	Wollstonecraft, Russell Street Bridge	007.449	007.503	Both	No Safe Place	No safe place	Lookout working not permitted
North Shore	St Leonards	008.290	008.360	Both	No Safe Place	Limited space to create a safe palce	Lookout working not permitted

Issued 10 January 2024 Review Date 10 January 2025

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
North Shore	Turramurra Station, Cherry St	020.900	21.010	Up	Safeworking	No Safe place	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Old Main So	uth Line		
Lookou • A safe • A safe	ut working place car track mu place car	LOOKO g on trac n easily st not be n be crea	OUT WO cks adja be reac e consid ated, for protecti	directi RKING All cent to p hed (clim dered and example ion on an	ion. ROUND PL latforms m bing onto o		itted when; rm from the), or
Old Main South Line	Granville- Merrylands	021.727	022.615	Down Old Main South line	Safeworking	No Safe place	Lookout working not permitted
Old Main South Line	Merrylands- Guildford	023.386	023.555	Down Old Main South line	Safeworking	No Safe place	Lookout working not permitted
Old Main South Line	Merrylands- Guildford	023.386	023.590	Up Old Main South line	Safeworking	No Safe place	Lookout working not permitted

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
Old Main South Line	Guildford- Yennora	025.251	025.600	Up Old Main South line	Safeworking	No Safe Place	Lookout working not permitted
Old Main South Line	Guildford- Yennora	025.898	026.227	Down Old Main South line	Safeworking	No Safe place	Lookout working not permitted
Old Main South Line	Yennora-Fairfield	29.000	29.400	Down Old Main South line	Safeworking	No Safe place	Lookout working not permitted

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions
				Port Kembla	Line		
				. Greatening			

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Issued 10 January 2024 Review Date 10 January 2025

NOTE: When

working within Yard Limits, Rail Traffic may approach from any direction								
Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions	
				Richmond	Line			
NOTE	· W/Is are see		didate V		Deil Treffi		la france and	
NOTE: When working within Yard Limits, Rail Traffic may approach from any								
direction. Schofields at 044.010kms to East Richmond at 059.506kms is Single								
				Line				
		LOOKO	UT WO	RKING AF	ROUND PLA	ATFORMS		
Lookou	ut working	on trac	ks adja	cent to pl	atforms ma	ay only be perm	nitted when;	

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions	
South West Rail Link								
NOTE	: When we	orking w	ithin Ya	ard Limits	s, Rail Traff	ic may approac	h from any	
				directi	on.			

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.

Issued 10 January 2024 Review Date 10 January 2025

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction

Corridor	Station / Location	Start	End	Lines Affected	Hazard	Description	Precautions		
Waverton to Lavender Bay									

NOTE: When working within Yard Limits, Rail Traffic may approach from any direction.

LOOKOUT WORKING AROUND PLATFORMS

- A safe place can easily be reached (climbing onto or under a platform from the track must not be considered and easily reached safe place), or
- A safe place can be created, for example, implementing ASB or a higher form of protection on an adjacent line.